

Secomak Ltd

Unit 330 Centennial Park, Centennial Avenue Elstree, Borehamwood, WD6 3TJ Web: <u>www.secomak.com</u> Email: <u>sales@secomak.com</u> Tel: 02087 321 300 Fax: 02087 321 301

8 October 2018

Protect Your Secomak Gas Booster

As a vendor or owner of a gas booster, now is the time to inspect it to ensure it operates effectively through the winter months.

Back in 1969, Secomak worked alongside British Gas to design and manufacture the first gas booster. We also sat on the board of directors to define the British Standards as they are today.

The latest British Standards BS8487:2007 & 2013 recommend:

- Drive Belts replace every year
- Bearing Assemblies replace every five years
- Flexible Connectors replace every five years

Whilst a component may appear in good working order, it pays to replace these serviceable parts on time, to reduce the risk of downtime.

T: 02087 321300

E: sales@secomak.com

W: https://www.secomak.com/product/gas-booster-maintenance

Sales: Nita McKenna

Marketing: Joss Piggott

